

PS. WAVERLEY: SURVEY AND REPAIR STRATEGY: 2005/6.

MONTH. 2005/6	DEC.				JAN.				FEB.				MARCH.				APRIL.				MAY.				JUNE.			
WEEK COMMENCING.	5	12	19	26	2	9	16	23	30	6	13	20	27	3	10	17	24	1	8	15	22	29	5	12	19	26		
Varnishing under cover.	←																											
Deck repairs & caulking.																												
External varnish work.																												
Varnish ship's side windows.																												
Painting - hull and s' structure.																												
- deck details.																												
Statutory dry-dock.																												
Jenny centre support repairs.																												
Belting & fascia repairs.																												
Boiler inspections.																												
NDT/repair paddle frames.																												
Loadline inspection.																												
Main engine survey & repair.																												
NDT starboard shaft.																												
Air pump survey & repair.																												
Pressure vessel survey.																												
Windlass survey & repair.																												
Capstan repair.																												
Electrical repairs - general.																												
Toilet mechanisms.																												
Toilet cubicle repairs.																												
Toilet cubicle painting.																												
Stability book & assessments.																												
Commissioning & drills.																												
Vessel in service.																												

Paintwork @ 51%

Vessel in service 100%

Deck 90%

Spot painting 100%

[Signature]
12/05.